S72	350	725/111	US-PGPUB;	OR	OFF	2005/06/06 15:42
		,	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB			
S73	326	725/111 not S63 not S61	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/06 15:41
S74	300	S73 not S49 not S52 not S54 not S56	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/06 15:42
S75	168	725/111 and (CTMS or (cable adj modem adj termination adj system))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/06 15:42
S76	0	("2003/0120819").URPN.	USPAT	OR	OFF	2005/06/06 15:44
S77	4	(MAC near5 synchroniz\$5) same ("fail over" "fail safe" "hot swappable" or (redundan\$3) fail)	USPAT	OR ·	OFF	2005/06/06 15:45
S78	1	"894748".apn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/07 10:26
S79		S78 and transmitter	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/07 10:27
S80	1	\$78 and receiver	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/07 10:30
S81	1	S78 and reset	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/07 11:03